

RISK ASSESSMENT												Ref: P010		
PPE (Selection & Use of)												Page 1 of 1		
EMPLOYER: Fastsource Ltd														
LOCATION: Calder Vale Road Wakefield														
ASSE:	SSED BY: B Ev	ans	<b>i</b>	DESIGNATION:	DESIGNATION: Yard Manager									
LEGEND: Likelihood and Severity:- 1 = Low 2 = Medium 3 = High Risk Rating (L x S):- 1-4 = Low (Acceptable) 6 = Medium (Consider further controls) 9 = Unacceptable (Do not proceed)														
RISK ASSESSMENT														
SIGNIFICANT HAZARDS IDENTIFIED: Give a brief description of what could be reasonably expected to cause significant harm and how that harm may arise.									NCONTROLLE			CONTROLLED		
•								L			RR	L	S	RR
Falls of materials onto unprotected limbs/ head									3	6		1	3	3
Inhalation of toxic or harmful substance								2	3	4		1	3	3
Cuts to hands or body								2	2	4		1	2	2
		_	ollision with plant		2				6		1	3	3	
	ge to eyes, dan							2	2	4	ļ	1	2	2
PERSC	ONS AT RISK: E	mpl	oyees undertaking act	ivitie	·S.									
			IVE EQUIPMENT: e required for the wor	k act	ivities stated. Ensure	the	correct TYPE of	PPE is	sel	ecte	d.			
Head Protection ✓ Eye/Face Protection ✓ He			Hearing Protection	<	Hi-visibility Cloth	thing ✓ Glov			Glove	es 🗸		<b>✓</b>		
Foot Protection   Safety Clothing R.F			R.P.E.	✓	Fall Arrest (in ME	EWP)								
CONTROL MEASURES:														
1.	All persons to o	onf	orm to site PPE rules.											
2.	All operatives are to ensure that skin remains covered during works. The wearing of shorts is strictly prohibited on all sites due to the nature of our operations. If skin comes into contact with any materials then it must be dealt with according to the manufacturer's recommendations immediately.													
3.	Hard hats to conform to the Construction Head Protection Regulations 1989. Any hat worn under a hard hat for warmth must be suitable to be worn with safety helmets, woollen hats/hoods/balaclava's not authorised for use with hard hats will not be permitted.													able
4.	Operatives to check job specific method and risk packages prior to commencing to ensure the required PPE is worn in conjunction with stated in the document.											n that		
5.	For RPE a qualitative fit testing is usually adequate for disposable filter face pieces and half-masks. This is undertaken as a simple pass/fail based on the wearers' subjective assessment of the fit and leakage. This method is not suitable for full-face masks. Any worn or damaged Items must be disposed off. Respiratory equipment - use an assigned protection factor of at least 20, even with water suppression equipment for cutting all silica based products use either FFP3 filtering face pieces or orinasal respirators with P3 filters. The risk assessment for the designated task should provide the type of RPE required.													
6.	Hearing protection must be provided were noise levels exceed 85db(A), equipment should be kept in a safe clean location, insertion plugs should be disposed of at the end of the working shift, cups should be kept clean and inspected for damage prior to use.													ıgs
7.	Safety footwear should be worn at all times whilst on site, with steel toecaps and a midsole; lace up boots/shoes should be worn to ensure good ankle support.													
8.	Where a COSHH assessment / risk assessment dictates gloves should be worn, these need to be free of damage and appropriate for the work being undertaken, all contaminated gloves should be disposed off.													
9.														
Remember: Always check in your safety manual for Company safety procedures and systems of work. Refer to other assessments for activities connected with this assessment.														nents
ADDI"	TIONAL CONTR	٥L ۸	MEASURES: (Review at v	vorkp	lace and add any addi	tiona	al specific controls	requir	ed)					
REVIEW AND MONITORING: Review in light of further information becoming available or a change in conditions/circumstances.														
INFORMATION TO BE PROVIDED TO EMPLOYEES: Information contained in this assessment.  SIGNED BY ASSESSOR: Robby Figure  DATE: November 2021													021	
SIGNI	ED BY ASSESSO	JK:	Bopph Frans							~,L	. 1100	CIIII	Jei Z	V